

Office of Executive Engineer Construction Division Building and Road Branch,
Sri Muktsar Sahib

Email ID: eccdmuktsarpwdpb@gmail.com

To,

The Principal,
Oracle International School,
Jandwala Charat Singh
Sri Muktsar Sahib

Dated: 17/6/25

Subject:- Regarding getting building safety certificate (Oracle International School,
Jandwala Charat Singh, Distt. Sri Muktsar Sahib

Reference: Your letter no. OIS/1761 /2025-26/143 Dated 09/06/2025

The inspection of your school has been done by Engineer Construction Sub Division No. 3, Malout and based on their report your school building is good to see and usable, therefore you are allowed to open the school based on the following criteria. The safety certificate of the civil work of the building is issued for the year 2025-26 (March 31, 2026).

1. This building should be renovated every year.
2. Water should not be allowed to store on and around the roofs of this building.
3. If there is any kind of crack in the building, that place should not be used and the place should be vacated immediately and the place should be repaired.
4. Safety in all aspects of the building will be the responsibility fo the organization, fire extinguishers should be in working order.
5. If the building is damaged due to any natural calamity or any other reason, this office should be informed immediately.
6. If any addition, is to be made in the building, it should be approved by the architect and this office should also be informed about it.
7. That school's fire certificate is due to expire on 02/09/2025. The school will be required to submit the fire safety certificate up to 31/03/2026 to this office immediately thereafter, falling which the safety certificate of this building will be considered cancelled.

Attached/ Certificate

Sd/- in English
Executive Engineer Construction Board
Sri Muktsar Sahib

Dated

A copy of the above is sent to Engineer Construction Sub Division No. 3 Malout for information in reference to his letter No. 238 dated 16/06/2025.


Principal,
Oracle International
Jandwala Charat Singh

Certified that this a true and
Correct. English translation
of a certificate/document
written in Punjabi Language

GURPUNEET KAUP
Advocate Notary Public
MALOUT 152107 (P)

Chairperson
Oracle Academy
Jandwala Charat Singh (Malout)

Sd/- in English
Executive Engineer Construction Board
Sri Muktsar Sahib



27 JUN 2025

Manager Razi Mahk
Oracle International School
Jandwala Charat Singh (Malout)

PROFORMA FOR THE SAFETY OF SCHOOL BUILDING

PART- 1

(To be filled by the Head of School/ Institute)

1. Name of the School : Oracle International School
2. Location : Jandwala Charat Singh The. Malout Distt. Sri Muktsar Sahib
3. Plot Area : $220' \times 198' = 43560$ sq. feet
4. Covered Area : Ground Floor 5660 sq. Feet , First Floor 5360 sq. Feet = 11020 sq. Feet
5. Number of Storey's : Two Storey
6. Year of Construction of Building : 2015 - 16 and 2016 - 17

7. If the building has been constructed under the supervision :
Of the qualified Engineer, the following details may be given

- a) Name of the Engineer with qualification : Er. Suresh Chetu (Civil Engineer)
- b) Address of Engineer : Teh. road Malout - 01637 - 503723
- c) Set of Structural drawings used in the construction, if available : Attached
- d) Name & address of Architect with qualification : Er. Suresh Chetu (Civil Engineer)
teh. road malout

8. Whether the building has been constructed for the purpose :

- a) School : YES/ NO
- b) Residential Purpose and converted for use as a School : YES/ NO

9. Materials used for roofs

- a) R.C.C. Slabs/R.B.C. Slabs : YES/ NO
- b) R.S. Joist & Battons : YES/ NO
- c) Wooden joists & Battons : YES/ NO

10. Materials used for walls

- a) Mud Mortar : YES/ NO
- b) Cement Mortar : YES/ NO
- c) Lime Mortar : YES/ NO

11. Flooring


- a) Conglomerate : YES/ NO
- b) Terrazo : YES/ NO
- c) Brick Paving. : YES/ NO

12. A detailed drawing indicating dimensions of the rooms : YES/ NO

Alongwith size and location of doors and windows (Attached)

13. FOR FIRE SAFETY

- a) Whether the width of the staircase is 1.5 mtr: YES/ NO.
- b) Whether portable fire extinguish exists YES/ NO
- c) Whether school building is free from inflammable and toxic material YES/ NO



[Signature]
Principal,
Oracle International School
Jandwala Charat Singh

[Signature]
Manager
Oracle International School
Jandwala Charat Singh (M)

Certified that this a true and
Correct. *[Signature]* translation
of a certificate/document
written in *[Signature]* language

GURPUNEET KAUR
Advocate Notary Public
MALOUT (52107) (DL)

27 JUN 2025
[Signature]
Chairperson
Oracle Academy
Jandwala Charat Singh (Malout)

(Contd.....2)

d) Whether cooking of food is done at safe place

YES/ NO

e) Whether any Thatch combustible material as been used

YES/ NO

14. Requirement for Fire Protection Arrangements under NBC

YES/ NO

PART - IV

(For Building Height less than 15 meter)

a) Whether Hose Real Provided

YES/ NO

b) Whether down comer provided

YES/ NO

c) Whether Automatic sprinkler provided

YES/ NO

d) Whether underground static water storage tank of capacity

YES/ NO

50,000 Ltr. (if covered area exceeds 1500 sqm.)

e) Whether overhead tank of capacity 10,000 Ltr. Exists (in case of hose real) 20 , 000


YES/ NO

f) Whether one electric and one diesel pump of capacity pressure of capacity 1620 LPM exist near underground static tank.

YES/ NO

g) Whether a pump 3 kg / cum pressure and 45C / 500 LPM exist near over head tank

YES/ NO



Principal,

Signature with stamp of the seal
Jandwala Charat Singh
of the school / Institution
(Shri Muktsar Sahib)

PART-II

(To be filled by the S.S.E. of PWD (B&R Department)

- a) I have visited the above mentioned school on dated 16/06/2021 And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be re obtained after the completion from the undersigned.
- c) In case the building is affected by food, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it is safe) 31/03/2026

Razi Habbu
Manager
Oracle International School
Jandwala Charat Singh (Malout)

Executive Engineer

Const. Divn. PWD(B&R) Br.

Shri Muktsar Sahib

Building is Safe through
vertical verification

Certified that this a true and
Correct. Translation
of a certificate/document
written in English Language

GURPREET KAUR
Advocate Notary Public

Sub Divisional Engineer

Const. Sub.Divn. PWD(B&R) Br.No.3.

Malout.

Chairperson
Oracle Academy
Jandwala Charat Singh (Malout)

27 JUN 2025